

# **HISTORIC AMERICAN ENGINEERING RECORD**

## **INDEX TO PHOTOGRAPHS**

ECHETA DAM & RESERVOIR

HAER WY-91

2.9 miles east of Echeta Road at Echeta Railroad Siding at County

Road 293

Echeta vicinity

Campbell County

Wyoming

## **INDEX TO BLACK AND WHITE PHOTOGRAPHS**

Richard Collier, photographer, March 2005

WY-91-1	OVERVIEW OF ECHETA DAM & SPILLWAY. TAKEN ABOVE THE DAM. TO NORTHWEST.
WY-91-2	OVERVIEW OF ECHETA DAM, WITH BREACH. VIEW TO SOUTHWEST.
WY-91-3	OVERVIEW OF DAM, SPILLWAY & QUARRY SITE. VIEW TO SOUTHWEST.
WY-91-4	ECHETA DAM SPILLWAY. VIEW TO NORTHWEST.
WY-91-5	ECHETA DAM SPILLWAY. VIEW TO SOUTHEAST.
WY-91-6	STONE RIP-RAP ON RESERVOIR SIDE OF DAM. VIEW TO SOUTHWEST.
WY-91-7	ECHETA DAM SHOWING BREACH AND DRAINAGE. VIEW TO NORTHWEST.
WY-91-8	STONE RIP-RAP ON RESERVOIR SIDE OF DAM. VIEW TO NORTH.
WY-91-9	ECHETA DAM BREACH AND DRAINAGE. VIEW TO NORTHWEST.
WY-91-10	ECHETA RESERVOIR BEHIND DAM. VIEW TO SOUTHEAST.

ECHETA DAM & RESERVOIR  
HAER WY-91  
INDEX TO PHOTOGRAPHS

WY-91-11	ECHETA DAM SPILLWAY. COMING OUT BELOW THE DAM. AT CENTER OF PHOTO. VIEW TO NORTHEAST.
WY-91-12	ECHETA DAM BREACH. SHOT FROM BELOW THE DAM. VIEW TO SOUTHEAST.
WY-91-13	ECHETA DAM RIP-RAP ON RESERVOIR SIDE OF THE DAM AT BREACH. VIEW TO NORTH-NORTHEAST.